


FS-OB MILLWORK RECOMMENDATIONS




IMPORTANT NOTES:

- Minimum alcove dimensions to be free of any obstructions.
- Power cord is in the rear of case with 4" clearance.
- Do not block intake or discharge air, observe clearance spaces


MODEL	CASE WIDTH	CASE DEPTH (With Clearance)	CASE HEIGHT	RECOMMENDED CUTOUT		
				DEPTH "A"	WIDTH "B"	HEIGHT "C"
FS-OB 1017-35A	36-1/4"	28-1/4"	32-1/2"	12-1/2"	34-1/2"	13"
FS-OB 1017-46A	47-1/4"	28-1/4"	32-1/2"	12-1/2"	45-1/2"	13"
FS-OB 1017-58A	59-1/4"	28-1/4"	32-1/2"	12-1/2"	57-1/2"	13"
FS-OB 1017-70A	71-1/4"	28-1/4"	32-1/2"	12-1/2"	69-1/2"	13"



TOP VIEW



FRONT VIEW



SIDE VIEW

